#### **Autonics**

## **Pressure Transmitter** PTF30 SERIES INSTRUCTION MANUAL





Thank you for choosing Autonics product Please read the following safety considerations before use.

#### Safety Considerations

XPlease observe all safety considerations for safe and proper product operation to avoid hazards. Safety considerations are categorized as follows.

**▲Warning** Failure to follow these instructions may result in serious injury or death.

▲Caution Failure to follow these instructions may result in personal injury or product damage

#### 

- 1. Fail-safe device must be installed when using the unit with machinery that may cause serious injury or substantial economic loss. (e.g. nuclear power control, medical equipment, ships, vehicles, railways, aircraft, combustion apparatus, safety equipment, crime/disaster prevention devices, etc.)
  Failure to follow this instruction may result in personal injury, fire, or economic loss.

  2. Check explosion-proof standard (Ex d IIC T6) of this unit and do not use it in place
- where there are flammable or explosive gas, humidity, direct ray the light, radiant heat, vibration and impact etc. Failure to follow this instruction may result in fire or explosion.
- Do not disassemble the case. Please contact us if it is required. Failure to follow this instruction may result in fire.

#### **⚠** Caution

- Do not apply beyond rated pressure.
   Failure to follow this instruction may result in product damage.
- 2. Use the unit within the rated specifications
- Failure to follow this instruction may result in shortening the life cycle of the unit, or fire. 3. Keep dust and wire residue from flowing into the unit.
- Failure to follow this instruction may result in product damage by fire 4. Wire it properly after checking terminal numbers when connecting power cable and
- measuring input. Failure to follow this instruction may result in product damage by fire
- 5. Please contact our service center if using for the corrosive detergent.
  Failure to follow this instruction may result in shortening the life cycle of the unit and product damage.
- 6. Do not use water or oil-based detergent when cleaning the unit. Use dry cloth to clean
- Failure to follow this instruction may result in electric shock or fire 7. The explosion-proof standard of this unit is Ex d IIC T6, protection structure of this unit is IP67 and the range of max. surface temperature is below 85°C.

### Ordering Information

PTF30 - G 7	N N	F8 (0 to 5kgf/cn	1^)			
① ② ③	4 5	6 7				
	Descrip	otion				
①Item	PTF30	Pressure Transmitter				
@Measurement	G	Gauge pressure				
pressure	Α	Absolute pressure				
		Absolute pressure, Gauge pressure		Gauge pressure		
	1	0 to 0.35kgf/cm <sup>2</sup>	7	0 to 70kgf/cm <sup>2</sup>		
	2	0 to 1kgf/cm <sup>2</sup>	8	0 to 200kgf/cm <sup>2</sup>		
	3	0 to 2kgf/cm <sup>2</sup>	9	0 to 350kgf/cm <sup>2</sup>		
0.5	4	0 to 7kgf/cm <sup>2</sup>	Α	-257mmHg to 0kgf/cm <sup>2</sup>		
③Pressure range	5	0 to 20kgf/cm <sup>2</sup>	С	-760mmHg to 0kgf/cm <sup>2</sup>		
	6	0 to 35kgf/cm <sup>2</sup>	F	-760mmHg to 2kgf/cm <sup>2</sup>		
			Н	-760mmHg to 7kgf/cm <sup>2</sup>		
		<b> </b>	M	-760mmHg to 20kgf/cm <sup>2</sup>		
			0	-760mmHg to 35kgf/cm <sup>2</sup>		
	Z	Others				
④HART communication output	N	None				
@Maxinting brookst	N	Without bracket				
	В	With bracket				
⑥Pressure port	F8	G3/8 (PF)				
⑦User pressure range		User pressure range*1				

\* 1: Write the desired pressure range and it is the default of user pressure range. (Select "Z" at ③Pressure range)

### Unit Descriptions





- 1. Display part: Displays detected pressure value,
- several setting value and errors.


  2. Unit display part: Displays the currently set input unit. 3. Output scale bar graph: Displays output DC4-20 mA as scale bar graph by 5% unit.
- 3 4. M key: Used to enter parameter mode, move parameters
- and save SV.

  5. ≪, ≫, № key: Used to enter parameter set mode, move digits.
- 6. D.IN3: Press the ⊠and ⊠keys at the same time for 3 sec, the set function (display HOLD, zero-point adjustment at d1 - K in parameter.

### Dimensions







\* The above specifications are subject to change and some models may be discontinued

#### Specifications Vapor, Liquid, Fluid (except corrosive environment of stainless steel 316) Measured materials Power supply 15-35VDC= 12-segment 4-digit LCD Display Display method W6.24×H10.73 mm (12-segment) / W1.45×H2.5 mm (unit) Character size DC4-20mA 2-wire Output Low-limit: 3.6 mA (-2.5%), High-limit: 21.6 mA (+10%) 10% of Span < URL: ± (0.05 + 0.015 URL/Span)% of Span Accuracy\*1 10% of Span ≥ URL: ±0.2% of Span Temperature At 20 °C, ± (0.075% × URL + 0.15% × Span) characteristics Setting by front push keys Setting method Sampling cycle 300 ms Dielectric resistance 1000 VAC for 1 min (between external terminal and case) 0.75 mm amplitude at frequency of 5 to 55 Hz (for 1 min) in each X, Y, Z Vibration direction for 2 hours Insulation resistance Over 100 MΩ (at 500VDC megger) Square shaped noise by noise simulator (pulse width 1 µs) ±240 V Noise immunity Approx. 10 years (non-volatile semiconductor memory type) Memory protection Environ- Ambient temp. -20 to 70 °C, storage: -20 to 80 °C Ambient humi. 0 to 85%RH ment Body: Aluminum (AIDc.8S), Cover O-Ring: Buna N, Material Diaphragm, connections: Stainless steel 316 Explosion class Ex d IIC T6 IP67 (IEC standard) Protection structure

\* 1: Span: User pressure range [ L - R 5 to H - R 5], URL: Pressure range by mode \* 2: This Explosion class is acquired and managed by Konics Co., Ltd.

#### Environment resistance is rated at no freezing or condensation. Functions

Approval

Unit weight

#### © Input unit [ IJNI Ł]

You can select input unit (bar, mbar, Pa, kPa, MPa, gf/cm<sup>2</sup>, kgf/cm<sup>2</sup>, mmH<sub>2</sub>O, psi, mmHg, %, OFF)

○ User input range [L-RG, H-RG]

1.2 kg

Even though each unit has the range, you can set user input range within the pressure range when input range is limited for actual usage

#### © Decimal point setting [ ຝ₽]


This function is to change decimal point digit for input display value. When input unit is set as  $(0.7 \circ 1)$  or OFF [ $0.7 \circ 1$ ], only the display position of decimal point is

• Setting range: 0 / 0.0 / 0.00 / 0.000

\* Setting range is different by the pressure range.

#### 

This function is to set (-1999 to 9999) for particular high/low limit value in order to display high/low limit value of measurement input. If measurement inputs are "a" and "b" and particular values are "A" and "B", it will display a=A, b=B as below graphs.



※ This function is available only when input unit is % [ ⁰ / ₀] or OFF [ ₀ F F ].

#### It corrects the error of display value for 0%

input. • Setting range: -999 to 999


# Output ▶ Input 0.00kgf/cm<sup>2</sup> 10.00kgf/cm


### It corrects the error of display value for 100% input. Setting range: 0.900 to 1.100 Output - Input

Slope correction [5PAN]

© Output scale [ L.o U + , H.o U + ]

For DC4-20 mA current output, this function is set to display value for current output. Set the display value for DC4 mA [ L.o U L ] and the display value for DC20 mA [ Ho U L ].





0.00kgf/cm<sup>2</sup>

10.00kgf/cm

□ Digital filter [ MAV.F ]

Digital filter is able to display stably and output the noise from input line and irregular signals. This unit applies moving average digital filter and display cycle is same • Setting range: 01 to 16

\* when setting as 01, digital filter function does not run.

### ⊚ Digital input [ ຝ≀ -к]

By front keys operation (D.IN3: 

+ ★ 3sec), one of two functions executes as the below

U	abie.		
	Function	ı	Operation
	HoLd		Temporarily indicated value is stopped in order to confirm indicated value in unstable input.
	Z-EM		It is same function as [ $\chi \in R_0$ ]. When executing this function, you can check and change correction value at $\chi \in R_0$ .


 Multi-display selection [ d5P I, d5P2]
 Select one for display 1 and display 2 among PV, oUE, LPEK, HPEK.
 Set d5P I and d5P2 differently and it displays two different values in turn for 2 sec. When selecting LPEK (HPEK), the left (or the right) of output scale bar graph flashes for 0.5

### High/Low peak monitoring [ L,PEK , H,PEK ]

This function is to save high/low peak to check the invisible abnormal condition of system Select this function display selection [ dSPI, dSP2] parameter. When the high/low peak is out of the temperature range, it displays HHHH or LLLL


To initialize high/low peak, press the ☑, ☒ keys at the same time for 3 sec at [ H.P.E.K.]or [ L.PEK ]. In this case, peak value is the present input value. © Two Unit Function [ ₺ 🛮 ₣ ]

For compound pressure model, this unction displays the input pressure which is below atmospheric pressure by mmHa unit. It displays the input pressure atmospheric pressure or over atmospheric pressure by the set pressure unit.



#### © Parameter initialization [ I NI E ] To initialize all parameter as factory default, cumply the no

pressing the M key and K key at the same time and it enters initialization parameter.



### □ Lock [L□[K]

It limits to check parameter set value and to change it

it infinite to direct parameter out value and to directly it.							
	oFF	LoC.I	L o C.2	Enable to check/set			
Parameter	•	0	0	Enable to check, disable to set     Disable to check			
L o E.2, only the L o E K parameter displays.							

### © Error

Display Descriptions Troubleshooting Flashes when measured pressure is higher than the нннн 'pressure range'. Adjust measured pressure lashes when measured pressure is lower than the within the 'pressure range' 'pressure range'. Re-set it after checking the Flashes when there is error to SV ERR setting conditions

#### Parameters

- ¥ 1. 

  S: Press any key among the 

  €, 

  Ø, 

  Ø
- \*\* 2. 低: Moves digits / 受, 為: Changes SV. \*\* 3. Press the M key after checking/changing SV in each parameter The value flashes twice and is saved. It moves to next parameter.
- 4. Defaults are different by the pressure range by each model.
   After entering setting group, press the M key for 3 sec or there is no additional key operation in 30 sec, it returns to RUN mode.
- This parameter may or may not appear, depending on the other parameter set. RUN mode M \*2 BAR ← MBAR ← PA ← KPA ← MPA ← G.EM Input unit ЬAR M ►PSI <del>Q</del>►MMH2 <del>Q</del>FKG.EM oFF **←→** º/o **◆**
- Low-limit input value

  \*4 L-R5

   Setting range: within the pressure range of input type
- ---- Setting range: within the pressure range of input type M
- Decimal point position

  \*4 d.P Select the decimal point position of display scale value. \* Setting range is different by the pressure range. L-5C **S** → 000.0


• Setting range: -1999 to 9999


- \* Displayed only when selecting input unit [ UNI E ] as M % [ º / o ] or OFF [ o F F ]. High-limit scale value H-5C • Setting range: -1999 to 9999 ※ Displayed only when selecting input unit [ UNI E ] as M
- % [ º / o ] or OFF [ o F F ]. Zero-point correct Corrects occurring error at 0% input.
  • Setting range: -999 to 999


Slope correction SPAN Corrects occurring error at 100% input. • Setting range: 0.900 to 1.100 M scale value s ..... Setting range: Within temperature range when input unit is standard pressure unit.

Within display scale range when input unit is % or OFF. High-limit output scale value

\*4 H.o U.L Setting range: Within temperature range when input unit is standard pressure unit. Within display scale range when input unit is % or OFF. Moving avera







INDICATOR RECORDER CONTROLLER  $\ominus$ F.G. \* You can check DC4-20 mA output by connecting an ampere meter. (impedance: max.  $30\Omega$ )

### Factory Default

Connections

l	Parameter	Default	Parameter	Default	Parameter	Default	Parameter	Default
l	UNI E	ьяк	L-50	0.00.0	L.oUt	0.000	dSP I	PV.
l	L-RG	0.0 0 0 <sup>×1</sup>	H-5C	100.0	H.oUE	0.350	d5P2	PV.
l	H-RG	0.350 *1	ZERo	000	MAV.F	04*1	E U F	oFF
l	d.P	0.350 *1	SPAN	1.000	dl -K	HoLd*1	LoEK	oFF
ı	W.A. Defaulte and different by the appearance by each model							

1: Defaults are different by the pressure range by each model.

### Cautions during Use

- For connecting the power, use a crimp terminal (M3.5, max. 7.2 mm).
   The connection of this unit should be separated from the power line and high voltage line in order to prevent inductive noise.
- 3. Install a power switch or a circuit breaker to supply or cut off the power
- 5. Do not use this unit near the high frequency instruments (high frequency welding machine & sewing machine, large capacity SCR controller). 6. When supplying input, if HHHH or LLLL is displayed, measured input may have problem.
- Turn off the power and check the line. Installation environment. 1 Indoor / Outdoor 2 Attitude max. 2,000 m
  3 Pollution degree 2 4 Installation category II
  8. Use verified explosion-proof electric connection (cable gland or sealing fitting).
- Use dedicated external terminal for earth. For connecting earth, use a spring washer and
   Use dedicated external terminal for earth. For connecting earth, use a spring washer and earth cable which is over 4mm<sup>2</sup>.
- \* We are not responsible for any damages and claims for careless. Must read the cautions for your safety and using.

  \*\* The explosion-proof unit is certified and the same specifications which is reported to
- Korea Gas Safety Corporation.

#### \* If there are any problems with the unit, contact the head office \* Failure to follow these instructions may result in product damage

### Major Products

Photoelectric Sensors	Temperature Controllers
Fiber Optic Sensors	Temperature/Humidity Transducers
Door Sensors	SSR/Power Controllers
Counters	
Area Sensors	Timers

- Area Sensors
  Proximity Sensors
  Pressure Sensors
  Rotary Encoders
  Connector/Sockets
  Subtbale Meta Dauce Supplies Switching Mode Power Supplies
- Control Switches/Lamps/Buzzers ■ I/O Terminal Blocks & Cables Stepper Motors/Drivers/Motion Controllers ■ Graphic/Logic Panels
  - Field Network Devices ■ Laser Marking System (Fiber Co. Nd: YAG) Laser Welding/Cutting Syste

# Autonics Corporation

Recorders

Converters

Controllers

■ Thyristor Units

■ Temperature Transmitters

■ HEAD QUARTERS: 18, Bansong-ro 513 beon-gil, Haeundae-gu, Busan, South

DRW171431BA